

# **COLANDER BISHOP**

## **ENTRANCE DOOR REPLACEMENT**

### **ADDENDUM #1**

- 1. There is a typo error in the specifications in relation to height size of doors. It states 6/0, it is 6/8 in height.**
- 2. On the form for contract bid the year date is 2018, it is 2019.**
- 3. Where it states continuous blocking with pressure treated wood, cancel. Once the door unit is removed and if there is damaged to the structural framing then pressure treated wood will be used for the damaged framing, all repairs will require a change order approved by the Facilities Manager.**
- 4. On the door Unit specifications #3 where pvc is stated, a composite material will be accepted.**

**Addition to specifications all doors will be require to have a "Ez Armor Security Combo Set with door shields " item code #SET-EZA-10000-BP**

## **LOCKS**

**Schlage Satin Chrome Elan Handel – Model #F10 ELA-626**

**Schlage Satin Chrome Deadbolt – Model #B60N-626**

**Keyed entry on exterior and thumb turn on interior.**

**Lock shall be keyed to existing SRHA lock set system.**

**One master key to open all doors and individual keys for the resident.**

**Provide ( 2 ) resident keys:**

**One labeled for manager extra.**

**One labeled for resident.**

**Front and back doors keyed alike.**